

Download 2003 Land Rover Discovery Repair Manual

We have launched Land Rover Hell www.LandRoverHell.com as a result of the consistent problems that we have experienced with our Land Rover Discovery since its purchase, almost 3 years ago. New Land Rover, Defender, Discovery 2 R/H Gearbox Mount, KQB500550 (14365) Fits:- All Discovery 2 Td5 & V8 models All Defender Td4 & Td5 models Only 89% breakdown free in 2003 Which survey. 2001 -2003 models average for breakdowns and poor for problems and faults in 2003 Which survey. Fuel tank problem on 2002 build TD5s put many off the road for months in late 2004 due to non availability of parts. New Discovery III late 2004. Came 13th The Series II Land Rover launched in 1958 was larger, heavier and more complex than the original, and there was an ever-present need for higher powered engines. Also, the Rover petrol engines in use at the time, with the archaic Inlet-Over-Exhaust valve layout and were approaching the age of 20 years in design terms.